

**MATERIAL SAFETY DATA SHEET**

**PRODUCT NAME: 6742 B TAPE**  
**PRODUCT CODE: 6742**

===== **SECTION I - MANUFACTURER IDENTIFICATION** =====

**MANUFACTURER'S NAME: LAMART CORPORATION**  
**ADDRESS: 16 RICHMOND ST. CLIFTON, N.J. 07011**  
**EMERGENCY PHONE: 973-772-6262**                      **INFORMATION PHONE: 973-772-6262**  
**DATE REVISED: 08/29/00**                                      **NAME OF PREPARER: PAF**

===== **SECTION II - HAZARDOUS INGREDIENTS / SARA III INFORMATION** =====

HAZARDOUS COMPONENTS	CAS NUMBER	OCCUPATIONAL EXPOSURE LIMITS			OTHER	VAPOR PRESS. mm.Hg @ TEMP.	WEIGHT PERCENT
		OSHA TLV	ACGIH TWA				
N/A							

N/A

**SUBJECT TO THE REPORTING REQUIREMENTS OF SECTION 313 OF THE EMERGENCY PLANNING AND THE  
 COMMUNITY RIGHT TO KNOW ACT OF 1986 AND 40 CFR 372.**

===== **SECTION III - PHYSICAL / CHEMICAL CHARACTERISTICS** =====

**MELTING RANGE: NA**    **SPECIFIC GRAVITY (H2O=1):1.2-1.8**  
**VAPOR DENSITY: NA**    **EVAPORATION RATE:NA**  
**HEATING VOC: NA**  
**HEAVY METAL VOC: NA**  
**SOLUBILITY IN WATER: NA**  
**APPEARANCE AND ODOR: BLUE FILM WITH A WHITE PAPER LINER, MILD ACRYLIC  
 ODOR**

===== **SECTION IV - FIRE AND EXPLOSION HAZARD DATA** =====

**FLASH POINT: 350 C**    **METHOD USED: ASTM D 1929**  
**FLAMMABLE LIMITS IN AIR BY VOLUME - LOWER: NA**                      **UPPER: NA**

**EXTINGUISHING MEDIA: FOAM, DRY CHEMICAL, WATER, CO2**

**SPECIAL FIREFIGHTING PROCEDURES:**  
**IF CONTAINED BREATHING APPARATUS IN CLOSE PROXIMITY OF FIRE.**

**UNUSUAL FIRE AND EXPLOSION HAZARDS:**  
**NONE**

**MATERIAL SAFETY DATA SHEET**

**===== SECTION V REACTIVITY DATA =====**

**STABILITY: STABLE**

**CONDITIONS TO AVOID: KEEP AWAY FROM HEAT FOR PROLONGED PERIODS**

**INCOMPATIBILITY (MATERIALS TO AVOID)**

**HAZARDOUS DECOMPOSITION OR BYPRODUCTS**

**CO, CO<sub>2</sub>, H<sub>2</sub>O, HYDROCARBONS AND THEIR OXIDES**

**HAZARDOUS POLYMERIZATION: WILL NOT OCCUR**

**===== SECTION VI - HEALTH HAZARD DATA =====**

**INHALATION HEALTH RISKS AND SYMPTOMS OF EXPOSURE**

**NO SIGNIFICANT HAZARDS UNDER NORMAL CONDITIONS OF USE, TOXIC FUMES ARE PRODUCED BY COMBUSTION.**

**SKIN AND EYE CONTACT HEALTH RISKS AND SYMPTOMS OF EXPOSURE**

**N/A**

**SKIN ABSORPTION HEALTH RISKS AND SYMPTOMS OF EXPOSURE**

**N/A**

**INGESTION HEALTH RISKS AND SYMPTOMS OF EXPOSURE**

**N/A**

**HEALTH HAZARDS (ACUTE AND CHRONIC)**

**N/A**

**CARCINOGENICITY: NTP?**

**N/A**

**IARC MONOGRAPHS?**

**N/A**

**OSHA REGULATED?**

**N/A**

**MEDICAL CONDITIONS AGGRAVATED BY EXPOSURE**

**NONE**

**EMERGENCY AND FIRST AID PROCEDURES**

**EYES: FLUSH IMMEDIATELY WITH WATER FOR AT LEAST 15 MINUTES. TAKE TO A PHYSICIAN FOR TREATMENT.**

**SKIN: N/A**

**INGESTION: DO NOT INDUCE VOMITING. CONSULT A PHYSICIAN IMMEDIATELY. TREAT SYMPTOMATICALLY.**

**MATERIAL SAFETY DATA SHEET**

**SECTION VII PRECAUTIONS FOR SAFE HANDLING AND USE**

**STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED  
PICK UP DEBRIS AND DISPOSE OF AS STANDARD SOLID WASTE, FOLLOW ALL EXISTING  
REGULATIONS FOR WASTE DISPOSAL IN YOUR AREA.**

**WASTE DISPOSAL METHOD**

DISPOSE OF IN ACCORDANCE WITH ALL LOCAL, STATE, AND FEDERAL REGULATIONS

**PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING**

N/A

**OTHER PRECAUTIONS**

N/A

**SECTION VIII CONTROL MEASURES**

**RESPIRATORY PROTECTION**

REQUIRED IF PROCESSING WITH HIGH HEAT ONLY

**VENTILATION**

ONLY IF PROCESSING WITH HIGH HEAT

**PROTECTIVE GLOVES**

TO AVOID CUTS

**EYE PROTECTION**

TO PROTECT FROM DUST

**OTHER PROTECTIVE CLOTHING OR EQUIPMENT**

N/A

**WORK / HYGENIC PRACTICES**

WASH HANDS BEFORE EATING OR USING RESTROOMS. REMOVE AND WASH CONTAMINATED CLOTHING BEFORE REUSE

**SECTION IX DISCLAIMER**

THE INFORMATION CONTAINED HEREIN IS FURNISHED WITHOUT WARRANTY OF ANY KIND. EMPLOYERS SHOULD USE THIS INFORMATION ONLY AS A SUPPLEMENT TO OTHER INFORMATION GATHERED BY THEM AND MUST MAKE INDEPENDENT DETERMINATION OF SUITABILITY AND COMPLETENESS OF INFORMATION FROM ALL SOURCES TO ASSURE PROPER USE OF THESE MATERIALS AND THE SAFETY AND HEALTH OF EMPLOYEES.